

**0800 183 490**

**021 183 4944**

**www.thermfit.nz**

**THERMFIT**  



FIJIAN

Ena vanua ni makete nikua na efficiency ni igu sa ikoya e dua na vosa ni buzz me voleka ni dua na cakacaka. Kevaka sara mada ga ni o biuta ena na vinaka duadua ni katubaleka kei na katuba, o rawa tikoga ni yali na kaukauwa ni ivalu ena veivanua tale eso ni itikotiko. Ena noda veiqraravi ni vakadidike sa rawa ni o raica na cava tale eso na veika o rawa kina na noda. Insulation ca, veilutuki tu na vakacakacakataki wavoki paipo kei na veivanua ni, na uca oqo kei na veika tale eso ena rawa me nomu katuba kei na katubaleka ni vakaduri raica me vaka ni oqo e sega ni vakayacori ki na veika e namaka. Imaging vutinisipi e vakayacori vata kei na dua infra-Damudamu katakata kidava na itaba ka sa vakaraitaka vakamatata na veivanua vanua katakata e mera dro mai kaukauwa. Era tu na veivanua e vuqa ni dua na vuvale me ni sereka na iwiliwili vakaitamera ni igu ikuri na katubaleka kei na katuba. Eda vakarautaka na voli ni maroroi taumada "Vutinisipi dikevi & suasua vakadidike" ka yavutaki ena Nelson ia veilakoyaki ena veiyasana.

In today's market place energy efficiency is a buzz word for almost any project. Even if you put in the best windows and doors, you can still be losing the energy battle in other areas of the home. Through our testing services you can see what other issues you may be having. Bad insulation, gaps around pipes and outlets, moisture penetration and other issues can make your door and window installation look like it is not performing to expectations. Thermal Imaging is performed with an infra-red heat sensitive camera that clearly shows areas where heat is escaping. There are many areas of a home that loose vast amounts of energy besides the windows and doors. We provide confidential pre-purchase "Thermal Inspections & Moisture Surveys" and are based in Nelson but travel the region.